

Bath and Body Works

Attrition Strategy: Implementation
Guide
2019





Program Objective

The Opportunity:

Integrate LED lamps into stores as a replacement for the following:

- ➤ Failed CMH track heads and/or CDM20 lamps
- Failed halogen Par 30 halogen lamps
- Failed MR16 halogen lamps /gimbal fixtures

The Strategy:

Strategic replacements listed below:

- For a failed CMH fixture or lamp: 1 to 1 replacement of the Green Creative Par 30 LED and gimbal set
- For a failed Par 30 halogen lamp: 1 to 1 replacement of the Green Creative Par 30 LED
- For a failed MR16 halogen lamp: Remove the existing lamp and gimbal and replace with a Green Creative Par 20 Lamp and gimbal

Keys to Success:

Full understanding at tech level of the following scenarios:

- Steps to take for track head failures
- Steps to take for recessed multiple failures
- Brand specific applications



BBW White CMH Fixture:



Or



CMH Fixtures









Green Creative 25 Degree Beam (Flood):



CDM 20 Fixtures





Green Creative 25 Degree Beam (Flood):

BBW Recessed Fixture:









Relamp with



Philips Mini Master CDM Lamp (RE-ORDER USING YOUR LAMP GUIDE)

If a ballast failures occurs in....









Replace with



Match Existing Ballast Type

BBW Misc. Lamps:



Par 30 Halogen Lamp



MR 16 Halogen Lamp and Gimbal Fixture

Replace with



Green Creative 25 Degree Beam (Flood):

Remove exiting lamp and fixture and replace with





Green Creative Par 20 and Contech Par 20 Gimbal